

TECHNICAL SANCTION FOR WORKS

Work Name : PPMS26-03-1000
Work Code : OD/350/3336/116944/399133/00086005
Work Category : Building/ Banking Facility Building
District Name : Cuttack
Block Name : Baranga
Gram Panchayat Name : Munduli
Village Name : Mundali

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 586316.50891964/- (Five lakh eighty six thousand three hundred sixteen rupees five zero eight nine one nine six four paise only), vide TSR No OD/350/3336/116944/399133/00086005/TS dated: 26-03-2026.

Technical sanction given by : Aditya Narayan Mishra(AEE), Baranga.