

BILLING DPR

State	Odisha	District	Kendujhar	Block	Joda	Gram Panchayat	Bolani
--------------	--------	-----------------	-----------	--------------	------	-----------------------	--------

Work Code	OD/361/3451/119441/385273/00057953 (REPAIR AND MAINTENANCE OF DUMURTA PRIMARY SCHOOL)
Project Category	Building

Financial Year	2020-21	Execution Level	PS
Executing Agency	Panchayat Samiti, Joda	Bill Status	Final Bill
Proposal Date	22-10-2021	Date of Commencement	13-10-2025
Date of Completion	17-10-2025	Scheme Name	5th SFC Grant in Aid
Scheme Component Name	Maintenance of Primary School Building	Project Sub-Category	Elementary School
Project Type	Repair and Maintenance	Name of Executant	

Administrative Approval Details

Approval No.	OD/361/3451/119441/385273/00057953/AS
---------------------	---------------------------------------

Technical Sanction Details

Technical Sanction No.	OD/361/3451/119441/385273/00057953/TS
Fund Sanction No.	328
Fund Sanction Amount (in Rs.)	200000

ROYALTY STATEMENT

Sl.No.	Activity Name/Material	Qty/unit (B=Analysis Basic Qty/Header Unit)	Quantity (Meaurement Qty)	Unit
1	Dismantling (AR1620) :.Dismantling and removing 2.5 cm thick grading concrete from roof - Dismantling and removing 2.5 cm thick grading concrete from roof slab cleaning the surface lowering and removing the debris within 50m lead and as per direction of Engineer-in-Charge.	-	74.465	Sqm
2	Concrete (AR0318) :.4cm thick grading concrete (1:2:4) on roof slab with 12mm size hard granite chips (Crusher Broken) - 4cm thick grading concrete (1:2:4) on roof slab with 12mm size hard granite chips (Crusher Broken) including hoisting and laying in position compacting and curing for the proper period with cost conveyance, royalty, taxes of all materials, labor and T&P required for the work etc. complete as per specifaion and direction of Engineer-in charge. (Old Work)	-	74.465	Sqm
i)	BRM340 : Cement	0.1287	9.5836455	1 Qntl.
ii)	BRM028 : Screened and washed sharp sand for mortar	0.018	1.34037	1 Cum

iii)	BRM064 : Granite stone broken chips of 4.7 mm size passing through 6.7 mm sieve (crusher broken.) and retained on 2.36 mm sieve.	0.018	1.34037	1 Cum.
iv)	BRM056 : Granite Stone broken chips 12mm. size (Minimum 65% by Wt. Passing through 13.2mm sieve & retained on 9.50mm sieve but whole should pass through 19mm sieve) (Crusher broken)	0.018	1.34037	1 Cum.
3	Plastering (AR1027) :.6mm thick cement Plaster in CM (1:4) over R.C.C. surfaces including chipping (Inside) - 6mm thick cement Plaster in CM (1:4) over R.C.C. surfaces in inside including chipping with proper level and line, curing for the proper period with cost conveyance, royalty, taxes of all materials, labor, and T & P required for the work, etc comp. and as per the direction of the Engineer-in-charge.	-	60.894	Sqm
i)	BRM340 : Cement	0.0372	2.2652568	1 Qntl.
ii)	BRM028 : Screened and washed sharp sand for mortar	0.0075	0.456705	1 Cum
4	Painting(AR0901d) :.Priming one coat with inner surface primer of approved quality water-bound primer over plastering surfaces (Inner surface) - Priming one coat with inner surface primer of approved quality water-bound primer over plastering surfaces including cost conveyance, taxes of all materials, labor and T&P required for the work complete as per direction of the Engineer-in-charge.	-	294.6105	Sqm
i)	BRM253 : Wall cement primer (I.S.I.) Water bound	0.084	24.747282	1 Ltr
5	Painting(AR0920) :.Finishing wall two coats with plastic emulsion paint of approved shades on new work (Inside) - Finishing wall two coats with plastic emulsion paint of approved shades on new work to give an even shade including all costs of labor, Paint and Brushes required for the work, etc. complete and as per direction of the Engineer-in-charge.(Inside)	-	294.6105	Sqm
i)	BRM140 : Plastic Emulsion paint	0.125	36.8263125	1 Litre
6	Painting(AR0918cb) :.Finishing wall two coats with weather coat with one coat waterbound Primer - Finishing wall two coats with weather coat with one coat waterbound Primer including all costs of labour, Paint, Primer, Brushes and putty required for the work etc. complete and as per direction of Engineer-in-charge.(Outside)	-	342.8205	Sqm
i)	BRM255 : Weather Coat (I.S.I.)	0.125	42.8525625	1 Ltr
ii)	BRM253 : Wall cement primer (I.S.I.) Water bound	0.090322580645161	30.964432258065	1 Ltr
7	Painting(AR0903b) :.Painting two coats of enamel paint with a coat of red oxide primer over iron surface - Painting two coats of enamel paint with a coat of red oxide primer over iron surface including all costs of labour, Paint, Primer, brushes and putty required for the work etc. complete and as per direction of Engineer-in-charge.	-	40.635	Sqm
i)	BRM137 : Red oxide Primer	0.054	2.19429	1 Litre
ii)	BRM141 : Enamel paint	0.125	5.079375	1 Litre

S/N	Material Name	Qty	Unit	Royalty Rate	Amount
1	BRM028	1.797075	1 Cum	50.25	90.30301875

2	BRM064	1.34037	1 Cum.	293.5	393.398595
3	BRM056	1.34037	1 Cum.	293.5	393.398595
					Total: 877.10020875