

ADMINISTRATIVE/FINANCIAL SANCTION FOR WORKS

Work Name : PPMS24-02-1000
Work Code : OD/350/3336/116944/399133/00085837
Work Category : Road/ CC Road
District Name : Cuttack
Block Name : Baranga
Gram Panchayat Name : Munduli
Village Name : Mundali

Considering Importance and necessity of the work and resolute by the District, Cuttack and Technically Approved / Sanctioned vide TSR No OD/350/3336/116944/399133/00085837/TS, Dt: 26-02-2026 the estimate of the proposed work has been accorded Administrative Sanction for Rs 266137.95182448/- (Two lakh sixty six thousand one hundred thirty seven rupees nine five one eight two four four eight paise only) vide Proceedings No. OD/350/3336/116944/399133/00085837/AS Dt: 26-02-2026.

Administrative sanction given by : Swagat Das(BDO), Baranga.