

## TECHNICAL SANCTION FOR WORKS

**Work Name :** PPMS11-02-5000  
**Work Code :** OD/350/3336/116944/399133/00085815  
**Work Category :** CD Work/ Slab Culvert  
**District Name :** Cuttack  
**Block Name :** Baranga  
**Gram Panchayat Name :** Munduli  
**Village Name :** Mundali

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 256574.18831646/-(Two lakh fifty six thousand five hundred seventy four rupees one eight eight three one six four six zero four paise only), vide TSR No OD/350/3336/116944/399133/00085815/TS dated: 10-02-2026.

**Technical sanction given by :** DEBASMITA LENKA, JE, Baranga.