

TECHNICAL SANCTION FOR WORKS

Work Name : REGRESSION06-03-5000
Work Code : OD/350/3336/116944/399133/00085884
Work Category : Building/ GP Bhawan
District Name : Cuttack
Block Name : Baranga
Gram Panchayat Name : Munduli
Village Name : Mundali

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 266207.58292757/- (Two lakh sixty six thousand two hundred seven rupees five eight two nine two seven five seven paise only), vide TSR No OD/350/3336/116944/399133/00085884/TS dated: 06-03-2026.

Technical sanction given by : DEBASMITA LENKA, JE, Baranga.