

TECHNICAL SANCTION FOR WORKS

Work Name : PPMS24-03-1000
Work Code : OD/350/3336/116944/399133/00085980
Work Category : Building/ GP Facility Centre
District Name : Cuttack
Block Name : Baranga
Gram Panchayat Name : Munduli
Village Name : Mundali

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 276480.04598289/- (Two lakh seventy six thousand four hundred eighty rupees zero four five nine eight two eight nine one three four paise only), vide TSR No OD/350/3336/116944/399133/00085980/TS dated: 24-03-2026.

Technical sanction given by : DEBASMITA LENKA, JE, Baranga.